




---

## MULTIPLE VENTING OF APPLIANCES

Not all "fan-assisted" furnaces have positive pressure at the appliance vent collar. These furnaces should be allowed to have their vent connector connect into the vent of other natural draft-type appliances (e.g. water heaters), as this will not be considered a violation of Section 802.10.3.2 of the County of Los Angeles Mechanical Code.

The nameplate on the furnace should be checked to determine if the furnace is Category I or II as these are the types that would have no positive pressure at the vent collar.

Supersedes MCM 815.3.2.7 (04/01/2003)

  
Carlos Clayton  
Chief Mechanical Inspector