




COMMON VENTING OF TWO DRAFT HOOD-EQUIPPED APPLIANCES

Where two draft hood-equipped appliances are connected to a common vent connector or manifold, the common vent connector shall be not less than the area of the larger vent connector plus 50 percent of the area of the smaller flue collar outlet.

All other cases of common venting shall comply with Section 803 of the County of Los Angeles Mechanical Code.


Carlos Clayton
Chief Mechanical Inspector